



VEHICLE INSPECTION REPORT

MH18OHG

Hyundai Kona 1.0T GDi Blue Drive Premium SE 5dr

nama
GRADE
2

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	13/06/2018	Body Style	Hatchback	Last service miles	30,381
Year	2018	Keys	2	MOT Due	16/01/2027
Mileage	38,197 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	7	Doors	5
VIN	KMHK3811LJU117049	Last service date	17/02/2025		

£100 ADDITIONAL FEE

Last Service - 17.02.2025 at 30381 miles (7 Main Dealer Services) Service due message displayed
Parking sensors faulty

Tyres

NSF	HANKOOK	3.0mm
NSR	HANKOOK	4.0mm
OSF	HANKOOK	4.0mm
OSR	HANKOOK	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Electric sunroof
- Electrically adjustable drivers seat
- Heated front seat
- Rear parking sensor
- Digital radio
- Front fog lights
- Electrically adjustable passenger seat
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
1 To 5



6: Door nsr
Scratched
UpTo 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Qtr Panel osr
Chipped
1 To 5



10: Wheel osr
Scratched
Up To 50mm



11: Door osr
Scratched
Over 25mm Thru Paint



12: Door osf
Chipped
Edge Chip



13: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		