



VEHICLE INSPECTION REPORT

LD73XYE

Honda E Ny1 150kW Elegance 69kWh 5dr Auto



Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	01/12/2023	Body Style	Hatchback	Last service miles	13,951
Year	2023	Keys	1	Gearbox	AUTOMATIC
Mileage	18,590 Miles Warranted	Service history	Yes	Gears	1
Fuel Type	Electric	Service documents	Printout	Doors	5
Colour	RED	Number of stamps	1		
VIN	LVHRS1856P5100133	Last service date	31/10/2025		

£100 ADDITIONAL FEE

Last service 31/10/2025 at 13,951 miles- 1 main dealer services Type 2 and 3 pin charging cables in boot

Tyres


NSF	BUDGET	6.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Poor Previous Repair
Poor Paint



5: Wheel nsr
Scratched
Over 50mm



6: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



8: Aperture Seal osr
Broken
Replace



9: Wing osf
Scratched
UpTo 25mm Thru Paint



10: Qtr Panel Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



11: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK