



VEHICLE INSPECTION REPORT

LD15MRO

Kia Venga 1.6 CRDi ISG 3 5dr

nama
GRADE
5

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/05/2015	Body Style	Hatchback	Last service miles	42,157
Year	2015	Keys	2	MOT Due	16/07/2026
Mileage	95,934 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	6	Doors	5
VIN	U5YEH814LFL115218	Last service date	22/06/2021		

£100 ADDITIONAL FEE

LAST SERVICE 22/06/2021 @ 42,157 MILES (6 SERVICES, ALL MAIN DEALER) Reverse camera faulty
Steering wheel knocking
Key getting stuck in ignition barrel

Tyres

NSF	LANVIGATOR	Damaged
NSR	FIRESTONE	Worn
OSF	GT RADIAL	6.0mm
OSR	ROYALBLACK	6.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Navigation system
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Dented
With Paint Damage



9: A Post ns
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Tailgate
Scratched
Over 25mm Thru Paint



13: Other
N/A
N/A



14: Wheel nsr
Scratched
Over 50mm



15: Wheel osr
Scratched
Over 50mm



16: Qtr Panel osr
Dented
Over 30mm



17: Door osr
Dented
Over 30mm



18: Door osf
Dented
Over 30% Of Panel



19: Wheel osf
Scratched
Over 50mm



20: A Post os
Scratched
Over 25mm Thru Paint



21: Roof
Rusted
Over 5mm

22: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK