



VEHICLE INSPECTION REPORT

GF12BZE

Ford S-Max 2.0 TDCi 140 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	03/04/2012	Body Style	MPV	Last service miles	143,884
Year	2012	Keys	2	MOT Due	14/07/2026
Mileage	145,731 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	9		
VIN	WF0SXXGBWSBM15301	Last service date	12/02/2026		

£90 ADDITIONAL FEE

Last service 12/02/2026 at 143,884 miles- 9 services. Book and print
 Mileages of services in 2020 to 2024 not recorded Engine malfunction message displayed
 Gearbox getting sticky
 Rubbing noise when car in full lock

Tyres

NSF	SAILUN	4.0mm
NSR	FALKEN	5.0mm
OSF	SAILUN	4.0mm
OSR	FALKEN	5.0mm

Spare

Features


- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm



4: Wing nsf
Dented
With Paint Damage



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Chipped
Multiple Chips



7: Qtr Panel nsr
Chipped
Over 5mm



8: Qtr Panel nsr
Dented
With Paint Damage



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Tailgate
Dented
With Paint Damage



11: Wheel osr
Scratched
Over 50mm



12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



13: Door osr
Dented
With Paint Damage



14: Sill os
Chipped
Over 5mm



15: Door osf
Chipped
Edge Chip



16: Wing osf
Dented
Between 10mm + 30mm



17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Over 50mm



19: Screen Front
Chipped
Up To 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK