46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU14KJE

Volkswagen Tiguan 2.0 TDi BlueMotion Tech Match 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	11/03/2014	**Body Style**	Estate	**Last service miles**	19,912
Year	2014	**Keys**	2	**MOT Due**	11/06/2027
Mileage	102,569 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	6
Colour	BLACK	**Number of stamps**	1	**Doors**	5
VIN	WVGZZZ5NZEW087587	**Last service date**	13/02/2015		

£90 ADDITIONAL FEE
LAST SERVICE 13/02/2015 @ 19,912 MILES (1 SERVICE)

Tyres

NSF	DUNLOP	4.0mm
NSR	DUNLOP	4.0mm
OSF	DUNLOP	Damaged
OSR	DUNLOP	4.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos




























Eastbourne Car Auctions

Condition Check



Damage Photos




1: Door osf
Dented
2 Or Less UpTo 10mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
Multiple Chips



4: Qtr Panel osr
Dented
Between 10mm + 30mm




5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Wing nsf
Dented
With Paint Damage



7: Door nsf
Chipped
Edge Chip




8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Bumper Front
Chipped
Multiple Chips



10: Bonnet
Chipped
1 To 5



11: Screen Front
Chipped
UpTo 10mm



12: Tyre osf
Punctured
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK