46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

EU65SRY

Audi A4 2.0 TDI Ultra 136 SE Technik 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	02/09/2015
Year	2015
Mileage	139,681 Miles Warranted
Fuel Type	DIESEL
Colour	SILVER
VIN	WAUZZZ8K6FA157331
Body Style	Estate

Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	6
Last service date	30/06/2022
Last service miles	111,055
MOT Due	07/07/2027

CAP Clean	£2,525.00
CAP Average	£2,100.00
CAP Below	£1,625.00
Gearbox	MANUAL
Gears	6
Doors	5

£90 ADDITIONAL FEE
CLUTCH REPLACED 22/06/2023
LAST SERVICE 30/06/2022 @ 111,055 MILES (6 SERVICES)

Tyres

NSF	LAUFENN	3.0mm
NSR	BARUM	3.0mm
OSF	BARUM	2.0mm
OSR	LAUFENN	4.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos









EU65 SRV




Switch off ignition before leaving car




Radio DAB
Capital DANCE
Capital UK
Capital XTRA
Classic FM
GB News Radio
Gold Radio UK










Condition Check




Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Dented
With Paint Damage



3: Headlamp os
Broken
Replace



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Chipped
1 To 5




7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Up To 50mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Up To 50mm



13: Door osr
Dented
Between 10mm + 30mm



14: Door osr
Scratched
UpTo 25mm Thru Paint



15: Door osf
Chipped
1 To 5



16: Wing osf
Poor Previous Repair
Rippled UpTo 30%



17: Wheel osf
Scratched
Over 50mm



18: Screen Front
Chipped
UpTo 10mm



19: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK