46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

DE14HTN

Vauxhall Insignia 2.0 CDTi [163] ecoFLEX Elite Nav 5dr [Start Stop]

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	09/07/2014	**Body Style**	Estate	**Last service miles**	29,346
Year	2014	**Keys**	2	**MOT Due**	Expired
Mileage	50,502 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	6
Colour	GREEN	**Number of stamps**	7	**Doors**	5
VIN	W0LGT8EM5E1127827	**Last service date**	06/03/2023		

MOT EXPIRED
LAST SERVICE 06/03/2023 @ 29,346 MILES (7 SERVICES) Camera image faulty
Smoking

Tyres

NSF	BUDGET	5.0mm
NSR	GRENLANDER	5.0mm
OSF	MAZZINI	5.0mm
OSR	FULLRUN	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos



















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Over 50mm



3: Tailgate
Scratched
Over 25mm Thru Paint



4: Wheel nsr
Scratched
Over 50mm



5: Door nsr
Dented
With Paint Damage



6: Door nsf
Dented
With Paint Damage



7: Wheel nsf
Scratched
Over 50mm



8: Bumper Front
Chipped
Multiple Chips



9: Bumper Front
Scratched
25 to 100mm Thru Paint



10: Other
N/A
N/A



11: Door osr
Scratched
UpTo 25mm Thru Paint



12: Qtr Panel osr
Chipped
1 To 5



13: Qtr Panel osr
Dented
2 Or Less UpTo 10mm




14: Bumper Rear
Chipped
Multiple Chips



15: Bumper Rear
Scratched
25 to 100mm Thru Paint



16: Sill ns
Dented
With Paint Damage



17: Bonnet
Chipped
1 To 5



18: Door osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK