46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GK70ASZ

Audi A3 30 TFSI S Line 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	24/10/2020	**Body Style**	Hatchback	**Last service miles**	19,272
Year	2020	**Keys**	2	**MOT Due**	Expired
Mileage	53,379 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	6
Colour	BLACK	**Number of stamps**	2	**Doors**	5
VIN	WAUZZZGY6MA023762	**Last service date**	01/07/2022		

£90 ADDITIONAL FEE
LAST SERVICE 01/07/2022 @ 19,272 MILES (2 SERVICES)
MOT EXPIRED

Tyres

NSF	BUDGET	5.0mm
NSR	NANKANG	5.0mm
OSF	NANKANG	Damaged
OSR	NANKANG	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels


Photos






















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door osr
Scratched
Over 25mm Thru Paint



4: Wheel osr
Scratched
Over 50mm



5: Qtr Panel osr
Dented
With Paint Damage



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Sill Panel Trim ns
Scratched (Painted)
Over 25mm Thru Paint



11: Door nsr
Scratched
UpTo 25mm Thru Paint



12: Wheel nsf
Scratched
Over 50mm



13: Wing nsf
Chipped
1 To 5




14: Bumper Front
Cracked
Over 25mm



15: Bumper Front Grill
Broken
Replace



16: Bonnet
Chipped
1 To 5



17: Screen Front
Chipped
UpTo 10mm



18: Roof
Scratched
Over 25mm Thru Paint



19: Tyre osf
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK