46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GX72XKS

Audi Q2 30 TFSI S Line 5dr

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	15/09/2022	**Body Style**	Estate	**CAP Below**	£11,950.00
Year	2022	**Keys**	2	**Gearbox**	MANUAL
Mileage	29,310 Miles Warranted	**Service history**	None	**Gears**	6
Fuel Type	PETROL	**MOT Due**	15/09/2027	**Doors**	5
Colour	GREY	**CAP Clean**	£14,200.00		
VIN	WAUZZZGAXNA054873	**CAP Average**	£13,050.00		

£90 ADDITIONAL FEE
NO SERVICE HISTORY.

Tyres

NSF	MAXXIS	5.0mm
NSR	CONTINENTAL	3.0mm
OSF	MAXXIS	5.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos











GK72 XKS


Short-term memory
Reset values with OK


Radio: DAB





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Scratched
Over 25mm Thru Paint



3: Wheel osr
Scratched
Over 50mm



4: Bumper Rear
Chipped
Multiple Chips



5: Wheel nsr
Scratched
Up To 50mm



6: Door nsf
Chipped
Edge Chip



7: Door nsf
Chipped
1 To 5



8: Wheel nsf
Scratched
Over 50mm



9: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



10: Bumper Front
Chipped
1 To 5



11: Bonnet
Chipped
1 To 5



12: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK