46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LY19KWN

Ford Ecosport 1.0 EcoBoost 125 Titanium 5dr Auto

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	28/03/2019	**Keys**	1	**CAP Clean**	£5,625.00
Year	2019	**Service history**	Yes	**CAP Average**	£4,875.00
Mileage	64,363 Miles Warranted	**Service documents**	Printout	**CAP Below**	£4,125.00
Fuel Type	PETROL	**Number of stamps**	3	**Gearbox**	AUTOMATIC
Colour	BLUE	**Last service date**	11/04/2024	**Gears**	6
VIN	WF01XXERK1JG67783	**Last service miles**	56,705	**Doors**	5
Body Style	Hatchback	**MOT Due**	20/04/2027		

£100 ADDITIONAL FEE
LAST SERVICE 11/04/2024 @ 56,705 MILES (3 SERVICES) EML light is on car has been plugged in and detects O2 heater circuit (Bank 1, sensor 2)

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	GT RADIAL	6.0mm
OSR	HANKOOK	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos








LT19 KWN




84363.0 mls
15°
Fuel level low
15 miles
to empty
P R N D S


3:55 15°
Controls


Preset bank: DAB 1
DAB
Sources
Sussex
Stations
10B
DAB station not available
Traffic (TA)
Presets
Hits
Audio
Phone
Navigation
Settings
TUNE



Ford Ecosport
LT19 KWN
Blue







Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Scratched
Over 25mm Thru Paint



3: Door osr
Chipped
1 To 5



4: Wheel osr
Scratched
Up To 50mm



5: Wheel nsr
Scratched
Up To 50mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Wing nsf
Poor Previous Repair
Poor Paint




8: Bumper Front
Scratched
UpTo 25mm Thru Paint



9: Bonnet
Poor Previous Repair
Poor Paint



10: Door nsr
Poor Previous Repair
Poor Paint



11: Roof
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK