46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LK21FGZ

Skoda Kodiaq 1.5 TSI SE Drive 5dr DSG [7 Seat]

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	25/03/2021	**Body Style**	Estate	**Last service miles**	24,294
Year	2021	**Keys**	2	**MOT Due**	24/03/2027
Mileage	51,485 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	7
Colour	BLACK	**Number of stamps**	2	**Doors**	5
VIN	TMBKB7NS9M8043507	**Last service date**	14/03/2024		

£100 ADDITIONAL FEE, LAST SERVICE 16-03-2024 @24294 MILES (2 SERVICES)

Tyres

NSF	PIRELLI	5.0mm
NSR	SUPERIA	5.0mm
OSF	NEXEN	6.0mm
OSR	SUPERIA	5.0mm
Spare		


Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos














BBC Radio 1 Anthems (DAB)







Wednesday 11:00am
Friday 6:00pm
www.ebca.co.uk



Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Dented
With Paint Damage



3: Door osr
Scratched
UpTo 25mm Thru Paint




4: Door osr
Chipped
1 To 5



5: Door osf
Scratched
UpTo 25mm Thru Paint



6: Wheel osr
Corroded
Light



7: Door osr
Chipped
Edge Chip



8: Bumper Rear
Chipped
Multiple Chips



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Qtr Panel nsr
Chipped
1 To 5



11: Door nsr
Scratched
UpTo 25mm Thru Paint



12: Door nsf
Scratched
Over 25mm Thru Paint



13: Wing nsf
Scratched
Over 25mm Thru Paint



14: Bumper Front
Scratched
25 to 100mm Thru Paint



15: Bonnet
Chipped
1 To 5




16: Screen Front
Cracked
Replace



17: Roof
Chipped
1 To 5



18: Tyre nsf
Damaged
Replace



19: Door osf
Chipped
1 To 5



20: Door nsr
Chipped
Edge Chip



21: Bumper Front
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK