46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

MA15XSP

Ford C-Max 1.6 TDCi Zetec 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	24/03/2015	**Body Style**	MPV	**Last service miles**	91,278
Year	2015	**Keys**	2	**MOT Due**	15/07/2027
Mileage	92,657 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	6
Colour	BROWN	**Number of stamps**	9	**Doors**	5
VIN	WF0JXXGCBJFC08951	**Last service date**	17/06/2026		

Last Service - 17.06.2026 at 91278 miles (9 main dealer Services)
All 4 Injectors Replaced 27.08.2025 @ 87069 Miles Odour when car running

Tyres

NSF	HANKOOK	5.0mm
NSR	HANKOOK	4.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features

- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos


























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Door osr
Chipped
1 To 5



4: Qtr Panel osr
Chipped
1 To 5



5: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



6: Bumper Rear
Chipped
1 To 5



7: Roof
Poor Previous Repair
Paint Flake



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
Between 10mm + 30mm



10: Qtr Panel nsr
Chipped
1 To 5



11: Door nsr
Chipped
Multiple Chips



12: Door nsf
Dented
Over 30mm



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
25 to 100mm Thru Paint



15: Bumper Front
Chipped
Multiple Chips



16: B Post ns
Poor Previous Repair
Paint Flake



17: Door osf
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK