46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KJ19WMP

Toyota RAV4 2.5 VVT-i Hybrid Excel 5dr CVT

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/05/2019	**Body Style**	Estate	**CAP Below**	£15,700.00
Year	2019	**Keys**	2	**Gearbox**	CVT
Mileage	55,896 Miles Warranted	**Service history**	None	**Gears**	1
		MOT Due	02/12/2026	**Doors**	5
Fuel Type	HYBRID ELECTRIC	**CAP Clean**	£18,400.00		
Colour	GREY	**CAP Average**	£17,050.00		
VIN	JTMDW3FV60D014160				

£100 ADDITIONAL FEE
NO SERVICE HISTORY

Tyres

NSF	BRIDGESTONE	6.0mm
NSR	DUNLOP	5.0mm
OSF	BRIDGESTONE	6.0mm
OSR	DUNLOP	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos









KJ19 HMP



16:26
PWR
ECO
CHG
OFF


Navigation
16:29
AUTO
OFF

FM
16:29
AUTO
OFF




Condition Check



Damage Photos



1: Other
N/A
N/A
Arm rest ripped



2: Bonnet
Chipped
1 To 5




3: Bumper Front
Chipped
1 To 5




4: Bumper Front
Scratched
25 to 100mm Thru Paint




5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door nsr
Dented
Between 10mm + 30mm
Multiple dents



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint




12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Door osr
Scratched
UpTo 25mm Thru Paint




15: Door osf
Chipped
1 To 5



16: Wing osf
Scratched
Over 25mm Thru Paint



17: Wheel osf
Scratched
Up To 50mm



18: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK