46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

YM18HZC

Volvo V60 T4 [190] R DESIGN Nav 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	20/07/2018
Year	2018
Mileage	55,404 Miles Warranted
Fuel Type	PETROL
Colour	BLACK
VIN	YV1FW41L1J2406551

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	6
Last service date	12/01/2026

Last service miles	48,666
MOT Due	11/01/2027
Gearbox	MANUAL
Gears	6
Doors	5

£90 ADDITIONAL FEE
Last Service - 12.01.2026 at 48666 miles (6 Services) Alarm malfunction message displayed

Tyres

NSF	KUMHO	Damaged
NSR	ACCELERA	5.0mm
OSF	KUMHO	1.0mm
OSR	ACCELERA	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- Rear wiper
- Radio/CD
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Partial leather seat trim
- Navigation system
- Service indicator
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos








YM18 HZC


















Alarm system malfunction
Service required
39.8
Ø mpg
14°c
11:20
Ø mph

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsr
Scratched
UpTo 25mm Thru Paint



7: Wheel nsr
Scratched
Up To 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint




10: Qtr Panel osr
Chipped
Over 5mm



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Chipped
Edge Chip




13: Door osf
Chipped
Edge Chip



14: Wing osf
Chipped
1 To 5



15: Wheel osf
Scratched
Over 50mm




16: Screen Front
Scratched
UpTo 30mm



17: Roof
Chipped
1 To 5



18: Tyre osf
Damaged
Replace



19: Tyre nsf
Damaged
Replace



20: Switches And Controls
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK