46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

YE64KXM

Nissan Juke 1.2 DiG-T Acenta Premium 5dr

Cat: S | Incident History

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/10/2014	**Body Style**	Hatchback	**Last service miles**	45,558
Year	2014	**Keys**	1	**MOT Due**	14/07/2027
Mileage	90,825 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	5
Colour	BLACK	**Number of stamps**	6	**Doors**	5
VIN	SJNFEAF15U7050050	**Last service date**	08/07/2022		

Category S Insurance Loss. Vehicle Structurally Damaged But Repairable-Insurer Decided Not to Repair
Last Service - 08.07.2022 at 45558 miles (6 Services)
Traction light on
Coolant leak

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim


Photos



















Eastbourne Car Auctions

Condition Check



Damage Photos




1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
Over 25mm Thru Paint



4: Door osr
Chipped
1 To 5



5: Wheel osr
Scratched
Over 50mm



6: Qtr Panel osr
Chipped
1 To 5



7: Bumper Rear
Chipped
Multiple Chips



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Qtr Panel nsr
Dented
Between 10mm + 30mm



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Door nsf
Dented
With Paint Damage



12: Wheel nsf
Corroded
Light



13: Wing nsf
Chipped
1 To 5



14: Bumper Front
Chipped
Multiple Chips



15: Bonnet
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm



17: Roof
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK