46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GL69MVV

Ford Focus 1.0 EcoBoost 125 Active X Auto 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	15/02/2020	**Body Style**	Hatchback	**Last service miles**	80,011
Year	2020	**Keys**	2	**MOT Due**	19/01/2027
Mileage	82,819 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	8
Colour	RED	**Number of stamps**	5	**Doors**	5
VIN	WF0NXXGCHNKU55333	**Last service date**	24/06/2026		

Last Service - 24.06.26 @ 80011 miles (5 services (4 main dealer))
Timing belt replaced 22.12.25 @ 75285 miles

Tyres

NSF	BUDGET	6.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BUDGET	6.0mm
OSR	BRIDGESTONE	5.0mm
Spare		


Features

- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim

Photos

























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Bumper Front
Chipped
Multiple Chips




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: A Post ns
Chipped
1 To 5



6: Screen Front
Chipped
UpTo 10mm



7: Door nsf
Chipped
Edge Chip



8: Door nsf
Dented
Between 10mm + 30mm




9: Door nsr
Dented
With Paint Damage



10: Qtr Panel nsr
Dented
With Paint Damage



11: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm




12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Boot Lid
Chipped
1 To 5



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Door osr
Dented
2 Or Less UpTo 10mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osf
Chipped
Edge Chip



18: Door osf
Scratched
UpTo 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm



20: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		