46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY65CZX

Volkswagen Golf 1.4 TSI GT 2dr DSG

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/10/2015	**Keys**	3	**CAP Clean**	£3,025.00
Year	2015	**Service history**	Yes	**CAP Average**	£2,550.00
Mileage	126,331 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£2,050.00
Fuel Type	PETROL	**Number of stamps**	14	**Gearbox**	SEMI AUTO
Colour	GREY	**Last service date**	13/10/2026	**Gears**	7
VIN	WVWZZZ1KZGK002205	**Last service miles**	126,052	**Doors**	2
Body Style	Convertible	**MOT Due**	29/10/2027		

£90 ADDITIONAL FEE
LAST SERVICE 13/10/2026 @ 126,052 MILES (14 SERVICES)

Tyres

NSF	HANKOOK	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	HANKOOK	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features

- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos













Eastbourne Car Auctions

Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Other
N/A
N/A
Armrest damaged




3: Seat Base Cover osr
Torn
Over 3mm



4: Seat Base Cover nsr
Torn
Over 3mm



5: Bonnet
Chipped
1 To 5



6: Bumper Front
Scratched
25 to 100mm Thru Paint



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Wheel nsf
Scratched
Over 50mm




9: Wing nsf
Dented
Between 10mm + 30mm



10: Wing nsf
Chipped
1 To 5



11: Flasher Side Repeater ns
Broken
Replace



12: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



13: Door nsf
Poor Previous Repair
Rippled UpTo 30%



14: Wheel nsr
Scratched
Over 50mm



15: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



16: Bumper Rear
Scratched
Over 100mm Thru Paint




17: Boot Lid
Chipped
1 To 5



18: Wheel osr
Scratched
Over 50mm



19: Qtr Panel osr
Dented
With Paint Damage



20: Door osf
Dented
Over 30mm



21: Wheel osf
Scratched
Over 50mm



22: Roof
Chipped
1 To 5



23: Boot Lid
Dented
Between 10mm + 30mm



24: Roof Soft Top
Scuffed
UpTo 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Poor	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK