46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU19KPY

Toyota RAV4 2.5 VVT-i Hybrid Design 5dr CVT 2WD

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	29/03/2019	**Body Style**	Estate	**Last service miles**	66,114
Year	2019	**Keys**	1	**MOT Due**	28/03/2027
Mileage	78,796 Miles Warranted	**Service history**	Yes	**Gearbox**	CVT
Fuel Type	HYBRID ELECTRIC	**Service documents**	Printout	**Gears**	1
Colour	WHITE	**Number of stamps**	7	**Doors**	5
VIN	JTMW23FV20J010743	**Last service date**	22/01/2026		

Last Service - 22.01.2026 at 66114 miles (7 main dealer Services)

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	RAPID	6.0mm
OSF	BUDGET	5.0mm
OSR	RAPID	6.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Cloth seat trim
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking


Photos



























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Door nsf
Poor Previous Repair
Rippled UpTo 30%



6: Door nsr
Dented
Over 30mm




7: Wheel nsr
Scratched
Up To 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Boot Lid
Dented
Over 30mm



10: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



11: Boot Lid
Scratched
Over 25mm Thru Paint



12: Qtr Panel osr
Dented
Between 10mm + 30mm



13: Door osr
Chipped
Edge Chip



14: Handle Outer osf
Scratched (Painted)
UpTo 25mm Thru Paint



15: Door osf
Chipped
Edge Chip



16: Wheel osf
Scratched
Up To 50mm



17: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK