46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU64EKF

Vauxhall Mokka 1.7 CDTi Exclusiv 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	12/09/2014
Year	2014
Mileage	95,323 Miles Warranted
Fuel Type	DIESEL
Colour	BLACK
VIN	W0LJC7EL8FB008124

Body Style	Hatchback
Keys	1
Service history	Yes
Service documents	Service Book
Number of stamps	7
Last service date	23/06/2022

Last service miles	53,201
MOT Due	11/01/2027
Gearbox	MANUAL
Gears	6
Doors	5

£90 ADDITIONAL FEE
Last Service - 23.06.2022 at 53201 miles (7 Services) Noisy clutch/ fly wheel

Tyres

NSF	HIFLY	2.0mm
NSR	BUDGET	5.0mm
OSF	HIFLY	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Service indicator
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos
























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Chipped
1 To 5



6: Bumper Front
Insecure
Action Required



7: A Post ns
Chipped
1 To 5



8: Door nsf
Dented
With Paint Damage



9: Door nsr
Poor Previous Repair
Rippled UpTo 30%



10: Wheel nsf
Scratched
Over 50mm



11: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Boot Lid
Scratched
UpTo 25mm Thru Paint



15: Bumper Rear
Scratched
25 to 100mm Thru Paint




16: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm




17: Spoiler Rear
Scratched (Painted)
Over 25mm Thru Paint



18: Qtr Panel osr
Dented
Over 30mm



19: Door osr
Dented
With Paint Damage



20: Door osf
Dented
Over 30mm



21: Other
N/A
N/A
Door and wing out of line



22: Wheel osf
Scratched
Over 50mm



23: Wing osf
Chipped
1 To 5



24: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK