46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU13DHP

Volkswagen Tiguan 2.0 TDi BlueMotion Tech SE 5dr DSG

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	16/03/2013	**Body Style**	Estate	**Last service miles**	63,178
Year	2013	**Keys**	2	**MOT Due**	06/04/2027
Mileage	65,747 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	7
Colour	BLACK	**Number of stamps**	13	**Doors**	5
VIN	WVGZZZ5NZDW052311	**Last service date**	23/04/2026		

£90 ADDITIONAL FEE
Last Service - 23.04.26 @ 63178 miles (13 main dealer services) Slight rattle coming from engine

Tyres

NSF	NEXEN	6.0mm
NSR	BRIDGESTONE	2.0mm
OSF	NEXEN	6.0mm
OSR	BRIDGESTONE	2.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels

Photos


















Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint




5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Dented
With Paint Damage



8: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Boot Lid
Scratched
UpTo 25mm Thru Paint




13: Door osr
Scratched
Over 25mm Thru Paint



14: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



15: Door osf
Chipped
Edge Chip



16: Door osf
Chipped
1 To 5



17: Wing osf
Chipped
1 To 5



18: Bumper Front
Insecure
Action Required



19: Seat Base Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		