46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

BL19XWO

Hyundai Tucson 1.6 GDi SE Nav 5dr 2WD

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/04/2019	**Keys**	2	**CAP Clean**	£7,200.00
Year	2019	**Service history**	Yes	**CAP Average**	£6,275.00
Mileage	54,844 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£5,375.00
Fuel Type	PETROL	**Number of stamps**	5	**Gearbox**	MANUAL
Colour	BLACK	**Last service date**	08/04/2026	**Gears**	6
VIN	TMAJ3811LKJ814309	**Last service miles**	50,751	**Doors**	5
Body Style	Estate	**MOT Due**	29/04/2027		

Last Service - 08.04.2026 at 50751 miles (5 Services)

Tyres

NSF	SUNNY	5.0mm
NSR	GOODYEAR	5.0mm
OSF	SUNNY	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos


























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Flasher Side Repeater ns
Broken
Replace



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: A Post ns
Scratched
Over 25mm Thru Paint



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Boot Lid
Scratched
Over 25mm Thru Paint



13: Bumper Rear
Scratched
25 to 100mm Thru Paint




14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Door osr
Chipped
Over 5mm



16: Door osf
Chipped
Multiple Chips




17: Door osf
Dented
Between 10mm + 30mm



18: Wing osf
Scratched
Over 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm



20: Screen Front
Chipped
UpTo 10mm



21: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK