46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

EK12MKZ

Mini Convertible 2.0 Cooper S D 2dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/03/2012	**Keys**	2	**CAP Clean**	£1,400.00
Year	2012	**Service history**	Yes	**CAP Average**	£1,000.00
Mileage	115,319 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£625.00
Fuel Type	DIESEL	**Number of stamps**	9	**Gearbox**	MANUAL
Colour	WHITE	**Last service date**	30/09/2020	**Gears**	6
VIN	WMWZR72090T147870	**Last service miles**	81,066	**Doors**	2
Body Style	Convertible	**MOT Due**	Expired		

Last Service - 30.09.2020 at 81066 miles (9 Services) Driver side front window need attention

Tyres

NSF	LANDSAIL	5.0mm
NSR	PIRELLI	5.0mm
OSF	LANDSAIL	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Service indicator
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Radio/CD
- Air conditioning
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos









EK12 MKZ




x1000
RPM
0
mph
268.4 mls












Condition Check



Damage Photos




1: Seat Back Cover osf
Scuffed
Over 25mm



2: Headrest Assy Rear Seat os
Missing
Replace



3: Bonnet
Chipped
Over 5mm



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Bumper Front
Chipped
1 To 5



6: Wheel nsf
Scratched
Over 50mm



7: Screen Front
Cracked
Replace



8: Door nsf
Dented
Over 30mm



9: Door nsf
Chipped
Edge Chip



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Bumper Rear
Dented
With Paint Damage



13: Qtr Panel osr
Dented
Between 10mm + 30mm
Multiple dents



14: Wheel osr
Scratched
Over 50mm



15: Door osf
Chipped
Edge Chip



16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




17: Door osf
Dented
Over 2 UpTo 10mm



18: Door osf
Scratched
Over 25mm Thru Paint



19: Wheel osf
Scratched
Over 50mm



20: Fascia Trim
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK