46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HT70CZG

BMW X6 xDrive30d MHT M Sport 5dr Step Auto

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	28/01/2021
Year	2021
Mileage	51,321 Miles Warranted
Fuel Type	ELECTRIC DIESEL
Colour	BLACK
VIN	WBAGT820309E70519
Body Style	Coupe

Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	4
Last service date	13/10/2025
Last service miles	43,395
MOT Due	29/01/2027

CAP Clean	£31,000.00
CAP Average	£29,650.00
CAP Below	£28,400.00
Gearbox	AUTOMATIC
Gears	8
Doors	4

£90 ADDITIONAL FEE
LAST SERVICE 13/10/2025 @ 43,395 MILES (4 SERVICES)

Tyres

NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	PIRELLI	Damaged
Spare		

Features

- Bluetooth connection
- Navigation system
- Radio/CD
- Air conditioning
- Cruise control
- Park assist camera
- Body coloured bumpers
- Climate control
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable drivers seat
- Heated front seat
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear electric windows
- Drivers airbag
- Central locking
- Rear headrests
- Passenger airbag
- Remote central locking

Photos




































Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door osr
Chipped
1 To 5



4: Door osr
Scratched
UpTo 25mm Thru Paint



5: Door osr
Chipped
Edge Chip



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Chipped
Edge Chip



10: Door nsf
Chipped
Edge Chip



11: Wheel nsf
Scratched
Over 50mm



12: Bumper Front
Scratched
25 to 100mm Thru Paint



13: Bonnet
Chipped
Multiple Chips



14: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



15: Screen Front
Chipped
UpTo 10mm



16: A Post os
Dented
With Paint Damage



17: Tyre osr
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		