46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

OE66ZNT

Vauxhall Mokka X 1.4T Active 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/01/2017	**Body Style**	Hatchback	**Last service miles**	93,875
Year	2017	**Keys**	2	**MOT Due**	16/10/2027
Mileage	94,380 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	6
Colour	BLUE	**Number of stamps**	5	**Doors**	5
VIN	W0LJC7E82HB027265	**Last service date**	30/09/2026		

Last Service - 30.09.2026 at 93875 miles (5 Services)

Tyres

NSF	AVON	5.0mm
NSR	AVON	5.0mm
OSF	AVON	5.0mm
OSR	AVON	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Digital radio
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim

Photos


















Eastbourne Car Auctions


Condition Check



Damage Photos




1: Centre Console Front
Scuffed
UpTo 25mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front Moulding
Broken
Replace



5: Bumper Front
Chipped
1 To 5




6: Wing nsf
Chipped
1 To 5




7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint




8: A Post ns
Chipped
1 To 5




9: Door nsf
Dented
2 Or Less UpTo 10mm




10: Door nsf
Chipped
1 To 5



11: Door nsr
Dented
Between 10mm + 30mm




12: Door nsr
Scratched
Over 25mm Thru Paint



13: Bumper Rear
Scratched
Up To 25mm Thru Paint



14: Boot Lid
Scratched
Over 25mm Thru Paint




15: Bumper Rear
Chipped
1 To 5



16: Door osr
Chipped
1 To 5



17: Door osf
Chipped
Edge Chip



18: Door osf
Chipped
1 To 5



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Up To 50mm



21: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK