46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HN70PNU

Ford Puma 1.0 EcoBoost Hybrid mHEV ST-Line 5dr

nama GRADE 2

Inspection		Vehicle	
Serious Damage?	No	**VAT**	Margin
		V5	Present

Details

Reg. date	30/09/2020	**Body Style**	Hatchback	**Last service miles**	51,458
Year	2020	**Keys**	2	**MOT Due**	29/09/2027
Mileage	52,570 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	6
Colour	GREY	**Number of stamps**	3	**Doors**	5
VIN	WF02XXERK2LA03284	**Last service date**	28/09/2026		

£100 ADDITIONAL FEE
Last Service - 28.09.26 @ 51458 miles (3 services)

Tyres

NSF	PIRELLI	5.0mm
NSR	GOODYEAR	5.0mm
OSF	PIRELLI	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features

- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels


Photos











13:43 10°
onto Manhall Road
3.1 mls
13:55
Eastbourne, England
Menu
Audio
Phone
Navigation
Mobile apps
Settings


13:43 10°
Sources
Stations
BBC RadioAnth...
Traffic (TA)
Now Playing: Hair by Little Mix feat. Sean Paul
BBC R1
BBC R&M
Capital
Absolute
Abs/R 90s
Audio
Phone
Navigation
Mobile apps
Settings



1470


ST-Line





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
1 To 5



3: Door osr
Chipped
1 To 5



4: Door nsr
Chipped
Edge Chip



5: Wheel nsr
Scratched
Up To 50mm



6: Bumper Front
Chipped
1 To 5



7: Bonnet
Chipped
1 To 5



8: Screen Front
Chipped
UpTo 10mm



9: A Post os
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK