

Vehicle Inspection Report

Date Inspected: 22/04/2025 16:56

Reg: GV21OSF

VIN: NMTK33BXX0R061945

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	TOYOTA	Body Type	Hatchback	Doors	5
Model	C-HR EXCEL HEV CVT - 1798cc	Fuel Type	Hybrid	Colour	White
Mileage	19110 miles	Transmission	Auto	Year of MFR	2021
				Date First Reg	29/06/2021

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	3 mm	Alloys	Yes
NSF Depth	3 mm	Alloys That Need Refurb	3
OSR Depth	6 mm	Tools	No
NSR Depth	4 mm	Spare	No Spare

Interior Condition








Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History


Service No History Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment					
	Wing osf Dented Between 10mm + 30mm Smart Repair		Door osf Dented Over 30mm Repair and Refinish		Bumper Rear Poor Previous Repair Poor Paint Refinish
	Door nsr Poor Previous Repair Poor Paint Refinish		Door nsf Poor Previous Repair Poor Paint Refinish		Bumper Front Scratched 25 to 100mm Thru Paint Smart Repair
	Door osr Chipped 1 To 5 Smart Repair				

Damage Lines			
Component	Condition	Severity	Repair
Wing osf	Dented	Between 10mm + 30mm	Smart Repair
Door osf	Dented	Over 30mm	Repair and Refinish
Bumper Rear	Poor Previous Repair	Poor Paint	Refinish
Door nsr	Poor Previous Repair	Poor Paint	Refinish
Door nsf	Poor Previous Repair	Poor Paint	Refinish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Door osr	Chipped	1 To 5	Smart Repair



Splat Key
S2 Scratch/Paint defect 30-100mm
D1 Dent/damage under 30mm
D2 Dent/damage 30-100mm
C2 Multiple Chips
PP Poor Previous

Comments
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.