

46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT



Land Rover Discovery Sport 2.0 SD4 240 HSE Luxury 5dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		C Grade
		V5	TBC		
Details					
Reg. date	22/10/2018	VIN	SALCA2AN2KH785909	CAP Average	£10,750.00
Year	2018	Body Style	Estate	CAP Below	£9,500.00
Mileage	62,232 Miles	Keys	2	Gearbox	AUTOMATIC
	Warranted	MOT Due	21/10/2025	Gears	9
Fuel Type	Diesel	CAP Clean	£11,950.00		
Colour	GREY				
Tyres					
NSF		HANKOOK		5.0mm	
NSR		BUDGET		5.0mm	
OSF		HANKOOK		4.0mm	
OSR		BUDGET		4.0mm	
Spare					

Features

Bluetooth connection

- Navigation system
- Rear wiper ٠ Digital radio
- Fixed panoramic glass roof • Electrically adjustable passenger • Front armrest
- seat
- Height adjustable drivers seat
- Metallic Paint ٠
- Isofix child seat anchor points
- Central locking
- Body coloured bumpers • Air conditioning

Cruise control

٠

•

- Rear armrest
- 3x3 point rear seat belts ٠
- Passenger airbag • Remote central locking

- · Front parking sensor

- · Leather seat trim

- · Heated front seat
- · Rear parking sensor
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Front head restraints
- · Rear headrests
- Drivers airbag
- Traction control
- · Alloy wheels

Photos



Eastbourne Car Auctions

Park assist camera • PAS

Steering wheel mounted controls . Trip computer

- Electric door mirrors •
- Climate control •
- Front electric windows

- ABS
 Side airbags

- · Rear electric windows










Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5

2: Bumper Front Chipped Multiple Chips

No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint





4: Bumper Front Moulding Scratched (Painted) Over 25mm Thru Paint

No Image

6: Wing nsf Scratched Over 25mm Not Thru Paint





7: Door nsf Chipped 1 To 5

No Image

8: Door nsf Scratched Over 25mm Not Thru Paint





9: Door nsr Chipped 1 To 5

10: Wheel nsr Scratched Up To 50mm

No Image

No Image

11: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



13: Boot Lid Chipped 1 To 5

12: Bumper Rear Scratched Over 25mm Not Thru Paint



14: Qtr Panel osr Chipped 1 To 5



No Image

15: Wheel osr Scratched Up To 50mm



16: Door osr Scratched Over 25mm Not Thru Paint

No Image

18: Wing osf Scratched Over 25mm Not Thru Paint

17: Door osf Chipped 1 To 5



19: Wheel osf Scratched Over 50mm

Interior

Eastbourne Car Auctions

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		