46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

YB09YJF

BMW X5 xDrive30d SE 5dr Auto [7 Seat]

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	21/08/2009	**VIN**	WBAFF42070L180764	**Gearbox**	AUTOMATIC
Year	2009	**Body Style**	Estate	**Gears**	6
Mileage	143,944 Miles Warranted	**Keys**	1	**Doors**	5
		Service history	None		
Fuel Type	DIESEL	**MOT Due**	12/01/2027		
Colour	GREY				

NO SERVICE HISTORY Transfer box fault
Instrument Cluster Fault

Tyres

NSF	ACCELERA	4.0mm
NSR	COMFORSER	5.0mm
OSF	ROYALBLACK	6.0mm
OSR	COMFORSER	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Digital radio
- Electric sunroof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Radio/CD
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Service indicator
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim

Photos















Navigation
On-board Info
Please insert Navigation DVD
Level control system failure!






Condition Check



Damage Photos



1: Door Pad osr
Scuffed
Over 25mm



2: Door Pad nsr
Scuffed
Over 25mm



3: Door Pad nsf
Scuffed
Over 25mm



4: Fascia Trim
Damaged
Replace



5: Bonnet
Chipped
Multiple Chips



6: Badgedecal Front
Missing
Replace



7: Bumper Front
Poor Previous Repair
Poor Paint




8: Other
N/A
N/A



9: Wing nsf
Poor Previous Repair
Poor Paint



10: Wheel nsf
Scratched
Over 50mm



11: Door nsf
Scratched
Rusted



12: Door nsr
Scratched
Over 25mm Thru Paint



13: Wheel nsr
Scratched
Over 50mm



14: Door nsr
Dented
Over 30mm



15: Lamp nsr
Broken
Replace




16: Tailgate
Poor Previous Repair
Poor Paint



17: Bumper Rear
Scratched
Over 100mm Thru Paint




18: Qtr Panel osr
Dented
Over 30mm



19: Wheel osr
Scratched
Over 50mm




20: Door osr
Dented
With Paint Damage



21: Door osf
Chipped
1 To 5



22: Wing osf
Poor Previous Repair
Poor Paint



23: Wheel osf
Scratched
Over 50mm



24: Screen Front
Chipped
Over 10mm



25: Other
N/A
N/A



26: Fascia Trim
Missing
Replace



27: Other
N/A
N/A

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		