46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KX68YSH

Volvo V60 2.0 D3 Momentum Pro 5dr Auto

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	22/11/2018
Year	2018
Mileage	80,207 Miles Warranted
Fuel Type	DIESEL
Colour	GREY
VIN	YV1ZW72UDK1017902

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	7
Last service date	10/11/2025

Last service miles	69,614
MOT Due	21/11/2026
Gearbox	AUTOMATIC
Gears	8
Doors	5

£90 ADDITIONAL FEE
Last Service - 10.11.2025 at 69614 miles (7 Services)

Tyres

NSF	MATADOR	6.0mm
NSR	MATADOR	Damaged
OSF	MATADOR	6.0mm
OSR	PIRELLI	Damaged
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos










KX68 YSH








13:28
Grt Hits Rad 80s
No phone paired
20°
AUTO
20°



13:28
Grt Hits Rad 80s
Hits Radio 90s
Hits Radio 00s
Classic FM
Capital XTRA
UCB 1
No phone paired
20°
AUTO
20°







Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Door osf
Dented
Over 30% Of Panel



4: Qtr Panel osr
Chipped
1 To 5



5: Wheel osr
Corroded
Light



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Door nsr
Chipped
1 To 5



9: Door nsf
Chipped
1 To 5



10: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




11: Wheel nsf
Scratched
Over 50mm



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Bonnet
Chipped
1 To 5



14: Screen Front
Chipped
UpTo 10mm



15: Tyre nsf
Damaged
Replace



16: Tyre osr
Damaged
Replace



17: Tyre nsr
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK