46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**AR19OCN**

## Citroen C3 1.2 PureTech 83 Flair 5dr

nama GRADE 2

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Reg. date** | 29/06/2019 | **Body Style** | Hatchback | **Last service miles** | 48,842 |
| **Year** | 2019 | **Keys** | 2 | **MOT Due** | 16/09/2027 |
| **Mileage** | 49,532 Miles Warranted | **Service history** | Yes | **Gearbox** | MANUAL |
| **Fuel Type** | PETROL | **Service documents** | Service Book | **Gears** | 5 |
| **Colour** | GREY | **Number of stamps** | 7 | **Doors** | 5 |
| **VIN** | VF7SXHMRVKT604125 | **Last service date** | 15/09/2026 | | |

Last Service - 15.09.26 @ 48842 miles (7 services)  Noisy engine

### Tyres

| | | |
|---|---|---|
| **NSF** | BUDGET | Damaged |
| **NSR** | LANDSAIL | 5.0mm |
| **OSF** | LANDSAIL | 5.0mm |
| **OSR** | LANDSAIL | 5.0mm |
| **Spare** | | |

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Park assist camera
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim


## Photos













99.90 MHz










# Condition Check




## Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Door osr
Dented
2 Or Less UpTo 10mm



5: Door osr
Chipped
Edge Chip




6: Qtr Panel osr
Dented
Between 10mm + 30mm



7: Bumper Rear
Chipped
1 To 5



8: Qtr Panel nsr
Poor Previous Repair
Poor Paint



9: Door nsr
Dented
Between 10mm + 30mm



10: Door nsf
Chipped
1 To 5



11: Bonnet
Chipped
1 To 5



12: Tyre nsf
Damaged
Replace

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | Fault | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |

| | | | |
|---|---|---|---|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |