46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

CY17PXU

Volvo XC60 D5 [220] SE Lux Nav 5dr AWD Geartronic

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	09/05/2017	**Body Style**	Estate	**Last service miles**	126,178
Year	2017	**Keys**	2	**MOT Due**	09/07/2027
Mileage	155,582 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	6
Colour	BLUE	**Number of stamps**	9	**Doors**	5
VIN	YV1DZ97C6H2171008	**Last service date**	19/12/2025		

TIMING BELT & WATER PUMP REPLACED 28/05/2025
LAST SERVICE 19/12/2025 @ 126,178 MILES (9 SERVICES)

Tyres

NSF	BUDGET	4.0mm
NSR	LAUFENN	5.0mm
OSF	BUDGET	4.0mm
OSR	LAUFENN	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Telephone
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking

Photos










GV17 PXU









LBC










Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Up To 50mm



8: Tailgate
Chipped
1 To 5



9: Bumper Rear
Poor Previous Repair
Poor Paint



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




12: Door osr
Chipped
1 To 5



13: Door osf
Dented
Between 10mm + 30mm



14: Door osf
Chipped
1 To 5



15: Screen Front
Chipped
UpTo 10mm



16: Roof
Chipped
Edge Chip



17: Bonnet
Dented
Over 30mm



18: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK