46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

BK13ETA

Honda CR-V 2.0 i-VTEC S 5dr 2WD

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	28/03/2013
Year	2013
Mileage	125,859 Miles Warranted
Fuel Type	PETROL
Colour	BROWN
VIN	SHSRE5730DU301461

Body Style	Estate
Keys	1
Service history	Yes
Service documents	Electronic / Online
Number of stamps	2
Last service date	19/08/2022

MOT Due	Expired
Gearbox	MANUAL
Gears	6
Doors	5

£100 ADDITIONAL FEE
LAST SERVICE 19/08/2022 @ UNKNOWN MILES (2 SERVICES, CONFIRMED BY SETYRES HASTINGS)

Tyres

NSF	RAPID	5.0mm
NSR	FALKEN	3.0mm
OSF	RAPID	5.0mm
OSR	FALKEN	3.0mm
Spare		

Features

- Bluetooth connection
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos

















Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Wheel osf
Scratched
Over 50mm



3: Door osf
Chipped
1 To 5



4: Door osr
Scratched
Over 25mm Thru Paint




5: Wheel osr
Corroded
Light



6: Qtr Panel nsr
Chipped
1 To 5




7: Wheel nsr
Corroded
Light



8: Door nsr
Chipped
Multiple Chips



9: Door nsf
Chipped
Edge Chip



10: Door nsf
Chipped
1 To 5




11: Wheel nsf
Scratched
Over 50mm



12: Bumper Front
Poor Previous Repair
Paint Flake



13: Bonnet
Chipped
1 To 5



14: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK