46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

DP73TFX

Vauxhall Corsa 1.2 Turbo GS 5dr

nama GRADE 3

Inspection		Vehicle	
Serious Damage?	No	**VAT**	VAT Qualifying
		V5	Present

Details

Reg. date	31/12/2023	**Body Style**	Hatchback	**Last service miles**	22,022
Year	2023	**Keys**	2	**MOT Due**	30/12/2026
Mileage	26,513 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	6
Colour	BLACK	**Number of stamps**	2	**Doors**	5
VIN	VXKUPHNEKP4300302	**Last service date**	20/11/2025		

£90 ADDITIONAL FEE
Last Service - 20.11.2025 at 22022 miles (2 Services)

Bonnet out of line

Tyres

NSF	HIFLY	5.0mm
NSR	MICHELIN	5.0mm
OSF	HIFLY	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

Photos









GF73 YFX






Apple CarPlay











Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Poor Previous Repair
Rippled UpTo 30%



6: Wheel nsr
Scratched
Over 50mm



7: Bumper Rear
Scratched
Up To 25mm Thru Paint



8: Qtr Panel osr
Chipped
1 To 5



9: Wheel osr
Scratched
Up To 50mm



10: Door osf
Chipped
Edge Chip



11: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



12: Wing osf
Chipped
1 To 5



13: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK