46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LO70DXC

Nissan Qashqai 1.3 DiG-T 160 [157] N-Connecta 5dr DCT Glass Roof

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	11/12/2020
Year	2020
Mileage	72,471 Miles Warranted
Fuel Type	PETROL
Colour	RED
VIN	SJNFFAJ11U2925804
Body Style	Hatchback

Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	1
Last service date	04/03/2023
Last service miles	42,456
MOT Due	24/11/2026

CAP Clean	£7,800.00
CAP Average	£6,850.00
CAP Below	£5,875.00
Gearbox	SEMI AUTO
Gears	7
Doors	5

Last Service - 04.03.2023 at 42456 miles (1 Services) Gearbox fault

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos





























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm




9: Qtr Panel nsr
Poor Previous Repair
Paint Flake



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Wheel osr
Scratched
Up To 50mm




12: Door osr
Dented
2 Or Less UpTo 10mm



13: Door osr
Chipped
1 To 5



14: Door osf
Chipped
Edge Chip



15: Glass Roof
Cracked
Replace



16: Lamp osr
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		