46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

BG18GJF

Nissan Qashqai 1.2 DiG-T N-Connecta 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/03/2018	**Body Style**	Hatchback	**Last service miles**	50,182
Year	2018	**Keys**	2	**MOT Due**	05/10/2027
Mileage	50,499 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	6
Colour	BLUE	**Number of stamps**	7	**Doors**	5
VIN	SJNFEAJ11U2232155	**Last service date**	26/09/2026		

£90 ADDITIONAL FEE
Last Service - 26.09.2026 at 50182 miles (7 Services)

Tyres

NSF	MAXXIS	4.0mm
NSR	MAXXIS	5.0mm
OSF	MAXXIS	4.0mm
OSR	MAXXIS	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels


Photos

















Eastbourne Car Auctions

Condition Check




Damage Photos




1: Wing nsf
Chipped
1 To 5



2: Door nsf
Chipped
Multiple Chips



3: Door nsr
Chipped
1 To 5



4: Door nsr
Chipped
Edge Chip



5: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



6: Tailgate
Chipped
1 To 5



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint



8: Door osr
Dented
With Paint Damage



9: Door osf
Chipped
1 To 5



10: Door osf
Chipped
Edge Chip



11: Wing osf
Scratched
UpTo 25mm Thru Paint



12: Wing osf
Chipped
1 To 5



13: Bumper Front
Chipped
Multiple Chips



14: Bonnet
Chipped
1 To 5



15: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK