46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

EU65YPG

Ford Ecosport 1.0 EcoBoost Zetec 5dr

nama GRADE 5

Inspection		Vehicle	
Serious Damage?	No	**VAT**	Margin
		V5	Present

Details

Reg. date	01/09/2015	**Keys**	2	**CAP Clean**	£1,400.00
Year	2015	**Service history**	Yes	**CAP Average**	£1,000.00
Mileage	95,191 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£600.00
Fuel Type	PETROL	**Number of stamps**	11	**Gearbox**	MANUAL
Colour	YELLOW	**Last service date**	24/09/2026	**Gears**	5
VIN	WF0BXXMRKBFS72876	**Last service miles**	95,016	**Doors**	5
Body Style	Hatchback	**MOT Due**	27/09/2027		

£100 ADDITIONAL FEE
Last Service - 24.09.26 @ 95016 miles (11 services)
Boot don’t open

Tyres

NSF	MICHELIN	4.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	4.0mm
Spare		

Features

- Bluetooth connection
- Radio/CD
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking

Photos













Condition Check




Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: A Post os
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Door osf
Chipped
1 To 5



5: Door osr
Chipped
Edge Chip



6: Qtr Panel osr
Dented
With Paint Damage




7: Tailgate
Dented
With Paint Damage



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Bumper Rear Moulding
Broken
Replace



10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Up To 50mm



12: Door nsr
Scratched
Over 25mm Thru Paint



13: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



14: Wheel nsf
Scratched
Up To 50mm



15: Wing nsf
Dented
With Paint Damage



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bonnet
Chipped
Multiple Chips



18: Roof
Chipped
1 To 5



19: Door nsf
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK