46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

SM14VMW

BMW X1 xDrive 18d xLine 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	16/07/2014
Year	2014
Mileage	137,677 Miles Warranted
Fuel Type	DIESEL
Colour	GREY
VIN	WBAVP72080VX44095
Body Style	Estate

Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	6
Last service date	05/09/2022
Last service miles	106,636
MOT Due	Expired

CAP Clean	£1,600.00
CAP Average	£1,175.00
CAP Below	£800.00
Gearbox	MANUAL
Gears	6
Doors	5

£100 ADDITIONAL FEE
Last Service - 05.09.22 @ 106636 miles (6 services)
Clutch replaced 20.11.20 @89640 miles Noisy engine

Tyres

NSF	INFINITY	5.0mm
NSR	INFINITY	5.0mm
OSF	INFINITY	4.0mm
OSR	LAUFENN	3.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos




























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Wheel osf
Scratched
Over 50mm




3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Door osr
Dented
Between 10mm + 30mm




7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Chipped
Multiple Chips



9: Qtr Panel nsr
Chipped
1 To 5



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Scratched
Up To 50mm



13: Wing nsf
Dented
Between 10mm + 30mm



14: Wheel nsf
Scratched
Over 50mm



15: Bumper Front
Chipped
Multiple Chips



16: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK