46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GJ65XVA

Peugeot 3008 1.6 BlueHDi 120 Allure 5dr EAT6

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Buyer To Apply

Details

Reg. date	15/01/2016	**Body Style**	Hatchback	**Last service miles**	94,675
Year	2016	**Keys**	2	**MOT Due**	29/03/2027
Mileage	95,550 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	6
Colour	GREY	**Number of stamps**	2	**Doors**	5
VIN	VF30UBHZTFS328281	**Last service date**	29/04/2026		

NO V5
LAST SERVICE 29/04/2026 @ 94,675 MILES (2 SERVICES) Eml light is on and UREA light is on
Car been plugged in and no fault code found

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim

Photos










GJ65 XVA





02:48
FEVERSEY
Visible satellites :

Check that the way is clear before moving

Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
Between 10mm + 30mm




9: Tailgate
Scratched
UpTo 25mm Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Scratched
Over 25mm Thru Paint



14: Wing osf
Chipped
1 To 5



15: Wheel osf
Scratched
Over 50mm



16: Tailgate
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK