46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

BJ62JXU

Mercedes-Benz C Class C220 CDI BlueEFFICIENCY Executive SE 5dr Auto

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	24/10/2012
Year	2012
Mileage	157,000 Miles Warranted
Fuel Type	DIESEL
Colour	BLACK
VIN	WDD2042022G013427
Body Style	Estate

Keys	1
Service history	Yes
Service documents	Printout
Number of stamps	12
Last service date	16/10/2025
Last service miles	145,004
MOT Due	Expired

CAP Clean	£1,675.00
CAP Average	£1,275.00
CAP Below	£875.00
Gearbox	AUTOMATIC
Gears	7
Doors	5

£100 ADDITIONAL FEE
LAST SERVICE 16/10/2025 @ 145,004 MILES (12 SERVICES) Noise from engine when idle but goes when revved
Eml light on car has been plugged in and detects diesel particulate filter soot accumulation

Tyres

NSF	LAUFENN	Damaged
NSR	HANKOOK	Damaged
OSF	LAUFENN	Damaged
OSR	LAUFENN	1.0mm
Spare		

Features

- Bluetooth connection
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Leather seat trim
- Cruise control
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos

























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Poor Previous Repair
Paint Flake



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
2 Or Less UpTo 10mm



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Scratched
UpTo 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Bumper Rear
Dented
With Paint Damage




11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Dented
Between 10mm + 30mm



14: Door osr
Chipped
1 To 5



15: Door osf
Dented
Between 10mm + 30mm



16: Door osf
Scratched
Over 25mm Thru Paint



17: A Post os
Chipped
1 To 5



18: Roof
Scratched
Over 25mm Thru Paint



19: Wing osf
Scratched
Over 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Tyre osf
Damaged
Replace



22: Tyre nsf
Damaged
Replace



23: Tyre nsr
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault
Airbag light illuminated	OK
ABS light illuminated	OK
Windows	OK

Oil warning light illuminated	OK
DPF light illuminated	OK
Service indicator light illuminated	OK
Radio	OK
Steering	OK