46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LE19WYZ

Ford Transit Custom 2.0 EcoBlue 105ps Low Roof D/Cab Trend Van

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Photocopy

Details

Reg. date	28/06/2019	**Body Style**	Panel Van	**Last service miles**	95,472
Year	2019	**Keys**	2	**MOT Due**	27/06/2027
Mileage	111,552 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	6
Colour	GREY	**Number of stamps**	3		
VIN	WF0ZXXTTGZKE33790	**Last service date**	16/02/2026		

Last Service - 16.02.2026 at 95472 miles (3 Services)
NO V5

Tyres

NSF	SAILUN	6.0mm
NSR	CONTINENTAL	Damaged
OSF	SAILUN	6.0mm
OSR	KORMORAN	6.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Front electric windows
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Metallic Paint
- Front parking sensor
- Digital radio
- Drivers airbag
- Heated front seat
- Air conditioning
- Central locking

Photos













Please check surroundings for safety


Smooth
Smooth C
Heart UK
Block 5A
Radio
Phone
Mobile apps
Settings


Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
With Paint Damage



6: Tyre nsr
Damaged
Replace



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
Over 25mm Thru Paint




9: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



10: Qtr Panel nsr
Chipped
1 To 5



11: Tailgate
Dented
With Paint Damage



12: Roof
Dented
Between 10mm + 30mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Panel Front
Dented
Over 30mm



15: Door osf
Scratched
Over 25mm Thru Paint



16: Wing osf
Chipped
1 To 5



17: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK