46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LR70FUH

Audi A3 35 TFSI S Line 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	15/09/2020	**Keys**	2	**CAP Clean**	£12,800.00
Year	2020	**Service history**	Yes	**CAP Average**	£11,700.00
Mileage	48,256 Miles Warranted	**Service documents**	Printout	**CAP Below**	£10,550.00
Fuel Type	PETROL	**Number of stamps**	4	**Gearbox**	MANUAL
Colour	BLACK	**Last service date**	25/07/2025	**Gears**	6
VIN	WAUZZZGY7MA019400	**Last service miles**	39,278	**Doors**	5
Body Style	Hatchback	**MOT Due**	14/09/2027		

£90 ADDITIONAL FEE
Last Service - 25.07.25 @ 39278 miles (4 main dealer services)

Tyres

NSF	NEXEN	3.0mm
NSR	CONTINENTAL	4.0mm
OSF	BRIDGESTONE	3.0mm
OSR	NEXEN	4.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels


Photos








LR70 FUH




Driver assist







DAB/FM
KISS
Pop
KISS DANCE
Pop
KISSTORY
Pop
KISS XTRA
Pop







Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Wheel osr
Scratched
Over 50mm




3: Wheel nsf
Scratched
Over 50mm



4: Bumper Front
Chipped
Multiple Chips



5: Bonnet
Chipped
1 To 5



6: Roof
Chipped
1 To 5



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Door nsf
Chipped
Edge Chip



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Scratched
Up To 25mm Thru Paint



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



12: Door osr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK