46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

WF67JPX

Kia Sportage 1.7 CRDi ISG 3 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	12/10/2017	**Body Style**	Estate	**Last service miles**	65,954
Year	2017	**Keys**	2	**MOT Due**	Expired
Mileage	69,625 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	6
Colour	BLACK	**Number of stamps**	7	**Doors**	5
VIN	U5YPH815LHL306937	**Last service date**	16/10/2025		

£90 ADDITIONAL FEE
Last Service - 16.10.25 @ 65954 miles (7 services)
MOT EXPIRED ABS and traction control light is on

Tyres

NSF	BUDGET	4.0mm
NSR	HABILEAD	5.0mm
OSF	BUDGET	4.0mm
OSR	RAPID	6.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim
- Cruise control
- PAS
- Digital radio
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos































Eastbourne Car Auctions


Condition Check




Damage Photos




1: Bumper Front
Cracked
UpTo 25mm



2: Bumper Front Moulding
Broken
Replace



3: Bumper Front
Poor Previous Repair
Poor Paint



4: Bonnet
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Tailgate
Scratched
Over 25mm Thru Paint




13: Wiper Rear
Broken
Replace



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint




15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
Over 30mm



17: Door osr
Scratched
UpTo 25mm Thru Paint



18: Door osf
Dented
Between 10mm + 30mm



19: Door osf
Scratched
Over 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
Chipped
1 To 5



22: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		