46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GH19NTD

Skoda Octavia 1.0 TSI SE Technology 5dr DSG

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	18/07/2019
Year	2019
Mileage	29,353 Miles Warranted
Fuel Type	PETROL
Colour	SILVER
VIN	TMBKP7NE5K0249947
Body Style	Estate

Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	5
Last service date	25/06/2026
Last service miles	28,384
MOT Due	17/07/2027

CAP Clean	£11,100.00
CAP Average	£10,050.00
CAP Below	£8,925.00
Gearbox	SEMI AUTO
Gears	7
Doors	5

£100 ADDITIONAL FEE
Last Service - 25.06.26 @ 28384 miles (5 services)

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos












MEDIA
PHONE
VOICE
APP
CAR
MENU
LO
LO
AUTO
A/C
SYNC
DSG


VOICE
MENU
Look! Safe to move?
LO
LO
AUTO
A/C
SYNC
MENU


0.0 / SET










Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Poor Previous Repair
Poor Paint



4: Door nsf
Chipped
Edge Chip



5: Bumper Rear
Scratched
25 to 100mm Thru Paint




6: Door osr
Chipped
Edge Chip



7: Door osf
Chipped
Edge Chip



8: Wing osf
Chipped
1 To 5



9: Screen Front
Scratched
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK