46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

AV65XOS

Ford Focus 1.0 EcoBoost 125 Titanium 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	11/12/2015	**Body Style**	Hatchback	**Last service miles**	58,852
Year	2015	**Keys**	2	**MOT Due**	10/12/2026
Mileage	80,651 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	6
Colour	BLUE	**Number of stamps**	8	**Doors**	5
VIN	WF05XXGCC5FM54070	**Last service date**	05/12/2024		

Last Service -05.12.2024 at 58852 miles (8 Services) EML light is on car has been plugged in and detects catalyst system efficiency below threshold bank 1

Tyres

NSF	MICHELIN	Illegal
NSR	FALKEN	4.0mm
OSF	MICHELIN	2.0mm
OSR	MICHELIN	4.0mm
Spare		

Features

- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos












13:03
BBC Radio2
SYNC
SOURCE
SOUND
DISP











Condition Check




Damage Photos




1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
1 To 5




3: Door osr
Chipped
1 To 5




4: Bumper Front
Scratched
UpTo 25mm Thru Paint



5: Bonnet
Chipped
Multiple Chips



6: Bumper Rear
Chipped
1 To 5



7: Door nsf
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK