46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

VU63KKX

Volkswagen Golf 2.0 TDI SE 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	12/09/2013	**Body Style**	Hatchback	**Last service miles**	155,481
Year	2013	**Keys**	2	**MOT Due**	04/12/2026
Mileage	158,781 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	6
Colour	RED	**Number of stamps**	3	**Doors**	5
VIN	WVWZZZAUZEW070943	**Last service date**	09/04/2026		

£90 ADDITIONAL FEE
Last Service - 09.04.26 @ 155481 miles (3 services)

Tyres

NSF	MICHELIN	4.0mm
NSR	MICHELIN	4.0mm
OSF	FIRESTONE	3.0mm
OSR	MICHELIN	4.0mm
Spare		

Features

- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm




5: A Post ns
Chipped
1 To 5



6: Roof
Chipped
Edge Chip



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Chipped
1 To 5



9: Qtr Panel nsr
Rusted
Over 5mm



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Boot Lid
Scratched
UpTo 25mm Thru Paint



13: Qtr Panel osr
Dented
Between 10mm + 30mm




14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Chipped
1 To 5



17: Door osf
Dented
Between 10mm + 30mm



18: Door osf
Chipped
1 To 5



19: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



20: A Post os
Chipped
1 To 5



21: Wheel osf
Scratched
Over 50mm



22: Wing osf
Chipped
Multiple Chips

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK