46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

VN12KWJ

Nissan Note 1.4 N-Tec+ 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Buyer To Apply

Details

Reg. date	25/04/2012	**Body Style**	MPV	**Last service miles**	18,521
Year	2012	**Keys**	2	**MOT Due**	26/03/2027
Mileage	52,843 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	5
Colour	BLACK	**Number of stamps**	4	**Doors**	5
VIN	SJNFAAE11U2165125	**Last service date**	21/01/2019		

£100 ADDITIONAL FEE
NO V5
LAST SERVICE 21/01/2019 @ 18,521 MILES (4 SERVICES)

Tyres

NSF	BUDGET	6.0mm
NSR	TRIANGLE	5.0mm
OSF	AUTOGREEN	5.0mm
OSR	BUDGET	Damaged
Spare		

Features

- Bluetooth connection
- Rear wiper
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Cruise control
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear parking sensor
- Digital radio
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking

Photos



























Eastbourne Car Auctions


Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint




6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: A Post ns
Scratched
UpTo 25mm Thru Paint



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Boot Lid
Dented
With Paint Damage



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm




16: Sill os
Dented
Between 10mm + 30mm



17: Door osr
Scratched
Over 25mm Thru Paint



18: Door osf
Scratched
Over 25mm Thru Paint



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm



21: Roof
Chipped
Edge Chip



22: Tyre osr
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK