46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

SB63DAB

Volkswagen Tiguan 2.0 TDi BlueMotion Tech R-Line 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	17/09/2013
Year	2013
Mileage	124,034 Miles Warranted
Fuel Type	DIESEL
Colour	WHITE
VIN	WVGZZZ5NZEW025799
Body Style	Estate

Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	14
Last service date	24/08/2026
Last service miles	123,251
MOT Due	16/09/2027

CAP Clean	£3,175.00
CAP Average	£2,700.00
CAP Below	£2,200.00
Gearbox	MANUAL
Gears	6
Doors	5

£90 ADDITIONAL FEE
LAST SERVICE 24/08/2026 @ 123,251 MILES (14 SERVICES, ALL MAIN DEALER) Power steering light abs light and traction light on

Tyres

NSF	NEXEN	4.0mm
NSR	NEXEN	6.0mm
OSF	NEXEN	4.0mm
OSR	NEXEN	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim

Photos






















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Poor Paint



2: Door osf
Dented
Between 10mm + 30mm



3: Door osf
Chipped
Edge Chip



4: Door osr
Dented
Between 10mm + 30mm



5: Qtr Panel osr
Chipped
1 To 5



6: Bumper Rear
Cracked
Over 25mm



7: Door nsr
Dented
Over 30mm



8: Other
N/A
N/A



9: Other
N/A
N/A



10: Bumper Front
Chipped
Multiple Chips



11: Bonnet
Chipped
1 To 5



12: Roof
Chipped
1 To 5



13: Roof
Rusted
UpTo 5mm



14: Door nsf
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	Fault