46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

AK13FPA

Volkswagen Passat 2.0 TDI Bluemotion Tech Sport 4dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	28/05/2013	**Keys**	1	**CAP Clean**	£1,800.00
Year	2013	**Service history**	Yes	**CAP Average**	£1,375.00
Mileage	127,150 Miles Warranted	**Service documents**	Printout	**CAP Below**	£925.00
Fuel Type	DIESEL	**Number of stamps**	2	**Gearbox**	MANUAL
Colour	BLUE	**Last service date**	25/11/2025	**Gears**	6
VIN	WVWZZZ3CZDE150940	**Last service miles**	120,132	**Doors**	4
Body Style	Saloon	**MOT Due**	28/11/2026		

LAST SERVICE 25/11/2025 @ 120,132 MILES (2 SERVICES) Eml light is on car been plugged in and detected coolant pump B control circuit / open

Tyres

NSF	BUDGET	Damaged
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Radio/CD
- Full size spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos




















Eastbourne Car Auctions

Condition Check




Damage Photos



1: Door Pad osf
Scuffed
Over 25mm



2: Tyre nsf
Damaged
Replace



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace



6: Flasher Side Repeater ns
Broken
Replace



7: Wheel nsf
Scratched
Over 50mm




8: Wing nsf
Chipped
1 To 5



9: Door nsf
Dented
With Paint Damage



10: Door nsr
Dented
Between 10mm + 30mm



11: Door nsr
Scratched
UpTo 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



14: Bumper Rear
Scratched
Over 100mm Thru Paint



15: Boot Lid
Chipped
1 To 5




16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Dented
With Paint Damage



19: Door osf
Scratched
Over 25mm Thru Paint



20: Wing osf
Scratched
Over 25mm Thru Paint



21: Wheel osf
Scratched
Over 50mm



22: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK