46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LD10YPU

Volkswagen Golf 1.4 TSI SE 5dr

Cat: D | Incident History

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	17/04/2010	**VIN**	WVWZZZ1KZAW343140	**Gearbox**	MANUAL
Year	2010	**Body Style**	Hatchback	**Gears**	6
Mileage	118,031 Miles Warranted	**Keys**	2	**Doors**	5
Fuel Type	PETROL	**Service history**	None		
Colour	BLUE	**MOT Due**	06/12/2026		

£100 ADDITIONAL FEE
D - Repairable Constructive Total Loss
NO SERVICE HISTORY Roof lining sagged

Tyres

NSF	BUDGET	4.0mm
NSR	GOODYEAR	4.0mm
OSF	BUDGET	4.0mm
OSR	GOODYEAR	3.0mm
Spare		

Features

- Heated front seat
- Electric door mirrors
- ABS
- Central locking
- Rear wiper
- Air conditioning
- Drivers airbag
- Remote central locking
- Radio/CD
- Climate control
- Passenger airbag
- Leather seat trim
- Body coloured bumpers
- Metallic Paint
- Traction control
- Alloy wheels

Photos














98.8 MHz
RADIO
MEDIA
TP
MENU

9:34

Condition Check




Damage Photos




1: Wheel osf
Corroded
Light



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Door osf
Scratched
UpTo 25mm Thru Paint



4: Door osf
Chipped
1 To 5



5: Door osf
Chipped
Edge Chip



6: Door osr
Poor Previous Repair
Poor Paint



7: Qtr Panel osr
Poor Previous Repair
Poor Paint



8: Wheel osr
Corroded
Light



9: Bumper Rear
Scratched
Over 100mm Thru Paint




10: Boot Lid
Scratched
UpTo 25mm Thru Paint




11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Corroded
Light



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Door nsf
Chipped
Edge Chip




15: Wing nsf
Chipped
1 To 5



16: Wheel nsf
Corroded
Light



17: Wing nsf
Dented
Between 10mm + 30mm



18: Bumper Front
Insecure
Action Required



19: Bonnet
Rusted
Over 5mm



20: Bumper Front
Cracked
Over 25mm



21: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK