46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

MT68FHR

Hyundai Tucson 1.6 GDi SE Nav 5dr 2WD

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/10/2018
Year	2018
Mileage	64,188 Miles Warranted
Fuel Type	PETROL
Colour	BLACK
VIN	TMAJ3811LKJ710173
Body Style	Estate

Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	7
Last service date	28/10/2025
Last service miles	58,407
MOT Due	21/09/2027

CAP Clean	£6,625.00
CAP Average	£5,750.00
CAP Below	£4,875.00
Gearbox	MANUAL
Gears	6
Doors	5

£100 ADDITIONAL FEE
LAST SERVICE 28/10/2025 @ 58,407 MILES (7 SERVICES, ALL MAIN DEALER) Gearbox not going in to second gear

Tyres

NSF	RAPID	6.0mm
NSR	BUDGET	5.0mm
OSF	RAPID	6.0mm
OSR	NANKANG	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: Wheel nsr
Scratched
Up To 50mm



10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Door osr
Scratched
Over 25mm Thru Paint



12: Door osf
Scratched
Over 25mm Thru Paint



13: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



14: Wing osf
Chipped
1 To 5



15: Screen Front
Chipped
UpTo 10mm



16: A Post os
Scratched
Over 25mm Thru Paint



17: Qtr Panel osr
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK